



FIG.1




THODS FOR CREATING PRINTING DATA
FOR TRANSFERRING PRINTING DATA
USSN No. 09/826,308
Darryl Mexic (202) 293-7060
2 of 11

2/11


FIG.2





3/11

FIG.3





• 	71a	72a 4	72b	72c	72 d	73a
HE	ADER	JOB START	PAGE START	PRINTING DATA 1	PRINTING DATA 2	FOOTER

<u>70b</u>

71b 5	72e 5	72 f	72 g	73b
HEADER	PRINTING DATA 3	PRINTING DATA 4	PRINTING DATA 5	FOOTER

<u>70c</u>

71c	72h 5	72 i	72 j	72k 5	721 5	73 c
HEADER	PRINTING DATA 6	PRINTING DATA 7	PRINTING DATA 8	PAGE END	JOB END	FOOTER




FIG.4A





FIG.4B







FIG.5







FIG.6






FIG.7A







FIG.7B





y 32 €

FIG.8







FIG.9







FIG.10






FIG.11



